


TECHNICAL INFORMATION



96468
May 2012

- Subject** ▶ Change of O-ring 60
- For Models** ▶ GN900
- Country** ▶ All countries
- Description** ▶ O-ring 60 has been replaced with cold resistant one.
See drawn below.
Service kit including the current O-ring 60 has been discontinued.
The cold resistant O-ring 60 is included to the new Service kit.

O-ring 60: 213677-4 → 213679-0



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
042	O-ring 60 213677-4	1	←	O-ring 60 213679-0	1	
—	Service kit 195154-7	1	←	Service kit 196234-2	1	The current service kit except O-ring 60 can be used for repair of GN900.

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

Implementation

From August 2012 MJ production