

# T ECHNICAL INFORMATION



94016  
December 2011

**Subject** ▶ Change of Spark unit

**For Models** ▶ GN900

**Country** ▶ All countries

**Description** ▶ Microcontroller program of Spark unit has been changed to improve the igniting action.

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
085	Spark unit ----- 631820-7		1	←	Spark unit ----- 620158-5		1	

### Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

## Implementation

After the current parts in stock are cleared